DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



tist

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

Partial: XXX Complete: Exploration: Inspection Date & Time: <u>5/11/2000 / 7:30a.m.-1:00p.m.</u>

Date of Last Inspection: 4/14/2000

Mine Name: Willow Creek Mine County: Carbon Permit Number: ACT/007/038						
Permittee and/or Operator's Name: Plateau Mining Corporation						
Business Address: 847 Northwest Highway 191, Helper, Utah 84526						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Vicky Miller						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: Sunny, Cold, 40's						
Existing Acreage: Permitted-14,670 Disturbed-161.55 Regraded- Seeded- Bonded-161.55						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_ Temporary Cessation/_ Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3. 4.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL HYDROLOGIC BALANCE.	EVALUATED [XX] [XX] [XX]	<u>N/A</u> ∐ ∐ ∐	COMMENTS [XX] [XX]	NOV/ENF
4. a. b. c. d.	HYDROLOGIC BALANCE: DIVERSIONS SEDIMENT PONDS AND IMPOUNDMENTS OTHER SEDIMENT CONTROL MEASURES WATER MONITORING EFFLUENT LIMITATIONS	[XX] [XX] [_] [_]			
5. 6. 7. 8.	EXPLOSIVES DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE PROTECTION OF FISH, WILDLIFE AND				
10. 11. 12. 13. 14.	RELATED ENVIRONMENTAL VALUES SLIDES AND OTHER DAMAGE CONTEMPORANEOUS RECLAMATION BACKFILLING AND GRADING REVEGETATION SUBSIDENCE CONTROL CESSATION OF OPERATIONS	[XX] [XX] [] [] [] []	[_] [_] [XX] [XX] [XX] [XX]		
16. a. b. 17. 18. 19. 20. 21.	ROADS: CONSTRUCTION/MAINTENANCE/SURFACING DRAINAGE CONTROLS OTHER TRANSPORTATION FACILITIES SUPPORT FACILITIES/UTILITY INSTALLATIONS AVS CHECK (4th Quarter-April, May, June) (date) AIR QUALITY PERMIT BONDING & INSURANCE	[XX] [XX] [XX] [XX] [] [] []			

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: 5/11/2000

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee is currently working on several submittals to amend certain areas of the currently approved mining and reclamation plan. These are:

- a) modification of the drainage plan on the School House Canyon refuse pile.
- b) modification of maps to correctly delineate the disturbed area perimeter in several locations. Ms. Miller showed several maps this day which will correct some errors in this perimeter which have existed for many years. All of the errors are on the preparation plant side of the disturbance (old Castle Gate permit); none are major.
- c) a revised reclamation plan for the Crandall Canyon area.

2. SIGNS AND MARKERS

The permittee has repainted the disturbed area perimeter markers in Gravel and Crandall Canyons using bright red paint; all are now clearly visible.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee has relocated the screening plant on the refuse pile to generate material for the ash fusion temperature enhancement process.

The use of coal mine waste as road base material at this site is currently under review at the UDNR/OGM/SLO. The material which will be used is the very hard white to gray sand rock which is native to the permit area.

9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES

During today's inspection, Ms. Miller informed me that an oil spill had occurred on May 4. Approximately 25 gallons of compressor oil were lost when a fitting from a hose blew off from the compressor located on the east side of the shop building, (main Mine facilities area). All of the spill was contained within a 14 X 14 foot area by Plateau personnel using floor dry absorbent. No oil entered any of the sites diversion ditches; none reached any navigable waters.

The expeditious handling of this issue can be accredited to internal training which the permittee has given to its employees.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Johnny Pappas (Plateau)	Henry Austin (OSM)
Given to: Pam Grubaugh-Liftig (DOGM)	Filed to: Price Field Office
Date: May 12, 2000	
Inspector's Signature: Little Hess	#46
Peter Hess	